



UL-CCIC Company Limited
No. 2, Chengwan Road, Suzhou Industrial Park, Suzhou 215122, China
T: + 86-512-6808 6400
F: + 86-512-6808 4099

No: 4790588239-2-S2

Issue Date:2022-10-10

Statement of Compliance

Project No.: 4790588239-2

Applicant: ZHEJIANG DAHUA VISION TECHNOLOGY CO.,LTD.

Address of Applicant: No.1199 Bin'an Road, Binjiang District, Hangzhou, P.R.China

Product Description: IP CAMERA

Series1: DH-IPC-HDW4841EM-S;IPC-HDW4841EM-S;DH-IPC-HDW4841EM-S-0280B;
DH-IPC-HDW4841EM-S-0360B;DH-IPC-HDW4841EM-S-0600B;IPC-HDW4841EM-S-0280B;
IPC-HDW4841EM-S-0360B;IPC-HDW4841EM-S-0600B;DH-IPC-HDW3841EM-S-S2;
IPC-HDW3841EM-S-S2;DH-IPC-HDW3841EM-S-0280B-S2;
DH-IPC-HDW3841EM-S-0360B-S2;DH-IPC-HDW3841EM-S-0600B-S2;
IPC-HDW3841EM-S-0280B-S2;IPC-HDW3841EM-S-0360B-S2;
IPC-HDW3841EM-S-0600B-S2;N84DGA2;N84DGA3;N84DGA6;
DH-IPC-HDW3841TM-S-S2;IPC-HDW3841TM-S-S2;DH-IPC-HDW3841TM-S-0280B-S2;
DH-IPC-HDW3841TM-S-0360B-S2;IPC-HDW3841TM-S-0280B-S2;
IPC-HDW3841TM-S-0360B-S2;Na3CJbcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
Na3CGbcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
Na3DGBcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
DH-IPC-HDW3866EMP-S-AUS;DH-IPC-HDW3866EM-S-AUS;IPC-HDW3866EMP-S-AUS;
DH-IPC-HDW3866EMP-S-AUS-BLK;DH-IPC-HDW3866EM-S-AUS-BLK;
IPC-HDW3866EM-S-AUS-BLK;Series2: DH-IPC-HDW4241EM-S;IPC-HDW4241EM-S;
DH-IPC-HDW4241EM-S-0280B;DH-IPC-HDW4241EM-S-0360B;
DH-IPC-HDW4241EM-S-0600B;IPC-HDW4241EM-S-0280B;IPC-HDW4241EM-S-0360B;
IPC-HDW4241EM-S-0600B;DH-IPC-HDW3241EM-S-S2;IPC-HDW3241EM-S-S2;
DH-IPC-HDW3241EM-S-0280B-S2;DH-IPC-HDW3241EM-S-0360B-S2;
DH-IPC-HDW3241EM-S-0600B-S2;IPC-HDW3241EM-S-0280B-S2;
IPC-HDW3241EM-S-0360B-S2;IPC-HDW3241EM-S-0600B-S2;N24DGA2;N24DGA3;
N24DGA6; DH-IPC-HDW3241TM-S-S2;IPC-HDW3241TM-S-S2;
DH-IPC-HDW3241TM-S-0280B-S2;DH-IPC-HDW3241TM-S-0360B-S2;
DH-IPC-HDW3241TM-S-0600B-S2;IPC-HDW3241TM-S-0280B-S2;
IPC-HDW3241TM-S-0360B-S2;IPC-HDW3241TM-S-0600B-S2;
DH-IPC-HDW3249EM-S-LED-S2;IPC-HDW3249EM-S-LED-S2;
DH-IPC-HDW3249EM-S-LED-0280B-S2;DH-IPC-HDW3249EM-S-LED-0360B-S2;

Model No.:



UL-CCIC Company Limited

No. 2, Chengwan Road, Suzhou Industrial Park, Suzhou 215122, China

T: + 86-512-6808 6400

F: + 86-512-6808 4099

No: 4790588239-2-S2

Issue Date:2022-10-10

IPC-HDW3249EM-S-LED-0280B-S2;IPC-HDW3249EM-S-LED-0360B-S2;
Na3CJbcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
Na3CGbcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
Na3DGBcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
Series3: DH-IPC-HDW4441EM-S;IPC-HDW4441EM-S;DH-IPC-HDW4441EM-S-0280B;
DH-IPC-HDW4441EM-S-0360B;DH-IPC-HDW4441EM-S-0600B;IPC-HDW4441EM-S-0280B;
IPC-HDW4441EM-S-0360B;IPC-HDW4441EM-S-0600B;DH-IPC-HDW3441EM-S-S2;
IPC-HDW3441EM-S-S2;DH-IPC-HDW3441EM-S-0280B-S2;DH-IPC-HDW3441EM-S-0360B-S2;
DH-IPC-HDW3441EM-S-0600B-S2;IPC-HDW3441EM-S-0280B-S2;
IPC-HDW3441EM-S-0360B-S2;IPC-HDW3441EM-S-0600B-S2;N44DGA2;N44DGA3;N44DGA6;
DH-IPC-HDW3441TM-S-S2;IPC-HDW3441TM-S-S2;DH-IPC-HDW3441TM-S-0280B-S2;
DH-IPC-HDW3441TM-S-0360B-S2;DH-IPC-HDW3441TM-S-0600B-S2;
IPC-HDW3441TM-S-0280B-S2;IPC-HDW3441TM-S-0360B-S2;IPC-HDW3441TM-S-0600B-S2;
DH-IPC-HDW3449EM-S-LED-S2;IPC-HDW3449EM-S-LED-S2;
DH-IPC-HDW3449EM-S-LED-0280B-S2;DH-IPC-HDW3449EM-S-LED-0360B-S2;
IPC-HDW3449EM-S-LED-0280B-S2;IPC-HDW3449EM-S-LED-0360B-S2;
DH-IPC-HDW3541TM-S-S2;IPC-HDW3541TM-S-S2;DH-IPC-HDW3541TM-S-0280B-S2;
DH-IPC-HDW3541TM-S-0360B-S2;DH-IPC-HDW3541TM-S-0600B-S2;
IPC-HDW3541TM-S-0280B-S2;IPC-HDW3541TM-S-0360B-S2;IPC-HDW3541TM-S-0600B-S2;
DH-IPC-HDW3541EM-S-S2;IPC-HDW3541EM-S-S2;DH-IPC-HDW3541EM-S-0360B-S2;
DH-IPC-HDW3541EM-S-0600B-S2;IPC-HDW3541EM-S-0280B-S2;
IPC-HDW3541EM-S-0360B-S2;IPC-HDW3541EM-S-0600B-S2;
DH-IPC-HDW3549EM-S-LED-S2;IPC-HDW3549EM-S-LED-S2;
DH-IPC-HDW3541EM-S-0280B-S2;DH-IPC-HDW3549EM-S-LED-0280B-S2;
DH-IPC-HDW3549EM-S-LED-0360B-S2;IPC-HDW3549EM-S-LED-0280B-S2;
IPC-HDW3549EM-S-LED-0360B-S2;
Na3CJbcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
Na3CGbcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
Na3DGBcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
DH-IPC-HDW3641EM-S-S2;IPC-HDW3641EM-S-S2;DH-IPC-HDW4541EM-S;
IPC-HDW4541EM-S;Na4DGBcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
DH-IPC-HDW3641EM-S-0280B-S2-AUS;DH-IPC-HDW3641EM-S-0360B-S2-AUS;
IPC-HDW3641EM-S-0280B-S2-AUS;IPC-HDW3641EM-S-0360B-S2-AUS;
DH-IPC-HDW4541EM-S-0280B;DH-IPC-HDW4541EM-S-0360B;
DH-IPC-HDW4541EM-S-0600B;IPC-HDW4541EM-S-0280B;
IPC-HDW4541EM-S-0360B;IPC-HDW4541EM-S-0600B;



UL-CCIC Company Limited

No. 2, Chengwan Road, Suzhou Industrial Park, Suzhou 215122, China

T: + 86-512-6808 6400

F: + 86-512-6808 4099

No: 4790588239-2-S2

Issue Date:2022-10-10

DH-IPC-HDW3641TM-S-S2;IPC-HDW3641TM-S-S2;DH-IPC-HDW3641TM-S-0280B-S2-AUS;
DH-IPC-HDW3641TM-S-0360B-S2-AUS;IPC-HDW3641TM-S-0280B-S2-AUS;
IPC-HDW3641TM-S-0360B-S2-AUS;DH-IPC-HDW3666EMP-S-AUS;
DH-IPC-HDW3666EM-S-AUS;IPC-HDW3666EMP-S-AUS;DH-IPC-HDW3466EMP-S-AUS;
DH-IPC-HDW3466EM-S-AUS;IPC-HDW3466EMP-S-AUS;DH-IPC-HDW3641EM-S-S2;
IPC-HDW3641EM-S-S2;DH-IPC-HDW4541EM-S;
IPC-HDW4541EM-S;Na4DGbcd(a=1~9; b=A~Z or 1~9; c=A~Z or 1~9; d=-B or blank);
DH-IPC-HDW3641EM-S-0280B-S2-AUS;DH-IPC-HDW3641EM-S-0360B-S2-AUS;
IPC-HDW3641EM-S-0280B-S2-AUS;IPC-HDW3641EM-S-0360B-S2-AUS;
DH-IPC-HDW4541EM-S-0280B;DH-IPC-HDW4541EM-S-0360B;
DH-IPC-HDW4541EM-S-0600B;IPC-HDW4541EM-S-0280B;IPC-HDW4541EM-S-0360B;
IPC-HDW4541EM-S-0600B;DH-IPC-HDW3641TM-S-S2;IPC-HDW3641TM-S-S2;
DH-IPC-HDW3641TM-S-0280B-S2-AUS;DH-IPC-HDW3641TM-S-0360B-S2-AUS;
IPC-HDW3641TM-S-0280B-S2-AUS;IPC-HDW3641TM-S-0360B-S2-AUS;
DH-IPC-HDW3466EMP-S-AUS-BLK;DH-IPC-HDW3466EM-S-AUS-BLK;
IPC-HDW3466EM-S-AUS-BLK; DH-IPC-HDW3666EMP-S-AUS-BLK;
DH-IPC-HDW3666EM-S-AUS-BLK; IPC-HDW3666EM-S-AUS-BLK;
DH-IPC-HDW3441TMP-S-0280B-S2-USA;DH-IPC-HDW3441TMP-S-0280B-S2-Black-USA;
DH-IPC-HDW3541TMP-S-0280B-S2-USA; N43CG62; N43CG62-B; N53CG62;

FCC RULES AND REGULATIONS PART 15 SUBPART B

EN 55032:2015+A1:2020

EN IEC 61000-3-2:2019

Test

Standard:

EN 61000-3-3:2013+A1:2019

EN 55035:2017+A11:2020

EN 55024:2010+A1:2015

EN 50130-4:2011+A1:2014

Test Report

Number(s):

4790588239-2-2



UL-CCIC Company Limited
No. 2, Chengwan Road, Suzhou Industrial Park, Suzhou 215122, China
T: + 86-512-6808 6400
F: + 86-512-6808 4099

No: 4790588239-2-S2
Issue Date:2022-10-10

This verification of EMC Compliance has been granted to the applicant based on the results of the tests, performed by laboratory of UL-CCIC Company Ltd. on the sample of the above-mentioned product in accordance with the provisions of the relevant specific standards and Directive 2014/30/EU. The CE mark as shown below can be used, under the responsibility of the manufacturer, after completion of an EC Declaration of Conformity and compliance with all relevant EC Directives.



Chris Zhong

Chris Zhong
EMC&RF Lab Operations Manager
UL-CCIC Company Limited.

Copyright of this verification is owned by UL-CCIC Company Ltd. and may not be reproduced other than in full and with the prior approval of the General Manager. This verification is subjected to the governance of the General Conditions of Services, printed overleaf.